

Installation Summary

Problem:

Excessive glare during the afternoon Intense sunlight impaired panoramic, scenic views

Potential for extensive fade damage of interior furnishings

Solution:

Solar Gard Panorama Slate 40 & Slate 30

Amount of flm:

Approximately 1,000 square feet

Benef ts:

Eliminated glare and hot spots Balanced temperature year-round Enhanced panoramic view of garden, terrace and lake

Protected against premature fading of interior furnishings

"Even icy, cold, northern climates beneft from Solar Gard® Panorama® by minimizing